

Office of the AGE B/R-I  
Military Engineer Services  
Kamptee-440001


2021/ THU /E2

Principal  
Kendriya Vidyalaya  
Kamptee-441001

22 Jul 2021

ISSUE OF SAFETY CERTIFICATE IN RESPECT OF KV SCHOOL KAMPTEE

1. Ref your letter No School Building/KV (Kmp)/2021-22/69 dt 10 Jun 2021.
2. With reference to the subject letter the undersigned has inspected the buildings of school and the following points are remedial measures suggested as under:-
  - (a) Visual inspection was carried and found that the structure is in good condition. The entire school building has been constructed in RCC framed structure. At places cracks developed in panels walls in ground floor and first floor (class rooms). The same panel walls in which cracks developed are required to be repaired.
  - (b) All crumple joints to be repaired, seepage at points to be done by treatment to sunken floors. Entire roof to be done water proofing treatment.
  - (c) Proper structural audit shall be carried out by non destructive test from approved testing NABL Lab.

  
(Sachin D Pande)  
AE (Civil)  
Asst Garrison Engineer

Copy to :-

Garrison Engineer - for info please.  
Kamptee-440001